ST MARY'S CHURCH DEDHAM

NEW ORGAN

PROGRESS REPORT

MAY 2024



NICHOLSON & CO. LTD MALVERN



Date of issue

2 May 2024

Safety

There have been 0 safety incidents and 0 near-misses on the project.

Design and planning

Detailed design of all parts of the organ is now complete.

Overview of activities undertaken in period

- Cleaning, measurement and repair of all manual pipework and some pedal pipework.
- Refurbishment of the console.
- Construction of reservoirs.
- Detailed design work.
- Construction of mobile console platform.
- Construction of pedal chests.

Overview of planned activities for next period

- Continued construction of pedal chests
- Continued refurbishment of the console

Decisions or information required from client

- None

Programme

No change from previously reported.



OVERALL PROGRESS AT A GLANCE

MECHANISM

Item	Dismantled/ removed	Design	Manufacture	Restoration	Installation
Wind system	removeu				
Blower		Complete	Ordered		Not started
Blower cabinet		Complete	Not started		Not started
Wooden wind		Complete	Not started		Not started
trunking					
Metal wind trunking		Complete	Not started		Not started
Great / Pedal		Complete	Complete		Not started
reservoir		-	_		
Swell reservoir		Complete	Complete		Not started
Swell tremulant			Complete		Not started
Conveyancing		Complete	Not started		Not started
Underactions					
Great		Complete	Underway		Not started
Swell		Complete	Underway		Not started
Soundboards					
Great		Complete	Underway		Not started
Swell		Complete	Underway		Not started
Slider solenoids					
Great		Complete	Complete		Not started
Swell		Complete	Complete		Not started



Item	Dismantled/ removed	Design	Manufacture	Restoration	Installation
Chests					
Open Diapason 16' / Octave 8'		Complete	Complete		Not started
C1-F#7#					
Open Diapason 16' / Octave 8' G8-E17		Complete	Underway		
Open Diapason 16' / Octave 8' F18-D#28		Complete	Underway		
Sub Bass 16' / Flute 8' C1-G#9		Complete	Complete		Not started
Open Diapason 16' / Octave 8' E29-F42 AND Sub Bass 16' / Flute 8' A10-F42		Complete	Underway		Not started
Trombone 16' C1-G#21		Complete	Underway		Not started
Trombone 16' A22-F30		Complete	Underway		Not started
No. 1 Open Diapason 8' C1-A#11 odds		Complete	Underway		Not started



Item	Dismantled/ removed	Design	Manufacture	Restoration	Installation
No. 1 Open Diapason	Tenioveu	Complete	Underway		
8' C#2-B12 evens					
Hohl Flute 8'		Complete	Underway		
C1-A#11 odds		_			
Hohl Flute 8'		Complete	Underway		
C#2-B12 evens		-			
Expression box and					
building frame					
Expression box		Complete	Underway		Not started
Building frame		Complete	Complete		Not started
Casework				Not started	Not started
Console					
Bench		Complete	Not started		Not started
Keyboards and	Complete	Complete		Underway	Not started
thumb pistons	-				
Pedalboard and toe	Complete	Complete		Underway	Not started
piston sweep					
Drawstops and jambs	Complete	Complete		Underway	Not started
Frame	Complete	Complete		Underway	Not started
Electrical systems		Complete	Not started		Not started
Cladding	Complete	Complete	Not started		Not started
Platform		Complete	Complete		Not started



PIPEWORK

Item	Dismantled/ removed	Design	Manufacture	Restoration	Regulated / voiced in workshop	Installation and tonal finishing
Pedal						
Open Diapason	Complete			Underway	Complete	Not started
16' / Octave 8'						
Sub Bass 16' /	Complete			Complete	Complete	Not started
Flute 8'						
Trombone 16'	Complete			Complete	Not started	Not started
Great						
Bourdon 16'	Complete			Complete	Complete	Not started
No. 1 Open	Complete			Complete	Complete	Not started
Diapason 8'						
No. 2 Open	Complete			Complete	Complete	Not started
Diapason 8'						
Hohl Flute 8'	Complete			Complete	Complete	Not started
Dolce 8'	Complete			Complete	Complete	Not started
Octave 4'	Complete			Complete	Complete	Not started
Flute	Complete			Complete	Complete	Not started
Harmonique 4'						
Twelfth $2^2/_3$	Complete			Complete	Complete	Not started
Fifteenth 2'	Complete			Complete	Complete	Not started
Grave Mixture	Complete			Complete	Complete	Not started
III						
Trumpet 8'	Complete			Complete	Complete	Not started
Swell						
Lieblich	Complete			Complete	Complete	Not started
Bourdon 16'						




Item	Dismantled/ removed	Design	Manufacture	Restoration	Regulated/ voiced in workshop	Installation and tonal finishing
Open Diapason 8'	Complete			Complete	Complete	Not started
Gedact 8'	Complete			Complete	Complete	Not started
Viol d'Orchestre 8'	Complete			Complete	Complete	Not started
Celestes 8'	Complete			Complete	Complete	Not started
Salicet 4'	Complete			Complete	Complete	Not started
Piccolo 2'	Complete			Complete	Complete	Not started
Mixture III	Complete			Complete	Complete	Not started
Horn 8'	Complete			Complete	Complete	Not started
Oboe 8'	Complete			Complete	Complete	Not started



PROGRESS PHOTOS



Boards for chests engraved with stop names



Pedal chest construction – preparing grooving veneers





Pedal chest construction – preparing rackboards



Pedal chest construction – leathering motors





Pedal chest construction – setting up actions



Pedal chest construction – completd action





Pedal chest construction – assembling well and spine



Boards for chests ready for assembly





Refurbishing keys



New name plaque





New thumb pistons





Making wind controls




Making boards for soundboard power motors






Spines and wells for soundboards



Cover boxes to silence the magnets on chests






Swell Horn 8' on voicing machine



Swell Oboe 8' on voicing machine





Great Trumpet 8' being worked on



Working on the Open Diapason No. 18'





Cleaning the Hohl Flute 8'



Frame for swell box






Building frame and reservoirs assembled, with wind controls fitted



Levelling up ground frame






Open Diapason 16' pipes (partially repainted, still to complete) stayed up on their new chest, and being tested on the wind



Open Diapason 16' pipes being painted





Slider solenoid racks



New tremulant for Swell